



Comprehensive Groundwater Protection Evaluation
for the South San Francisco Bay Basins

Figure 28: Known Potential
Vertical Conduits

- Well, ca. 1915
- Cooley Landing wellfield (19 wells)
- Well destroyed without permit or inspection; destruction method unknown
- Abandoned well, no destruction information given
- No data
- Basin boundary
- Major road

Sources: Alameda County Water District; Santa Clara Valley Water District; San Mateo Environmental Health Services Division

